


## *Paragon M+ and V16 Options New optional productivity tools*

Maximize the productivity of your Gribetz Paragon® or V16™ quilter with new optional equipment. Improve your daily throughput and keep your equipment running longer.



\* Some options may be limited to specific machine models. Consult your GSG representative for full details.

*A great deal of value in every machine*



Language-independent icons for maintenance tasks.



Informative guides on the machine for maintenance operations.



Visual charts to track and alert you of maintenance status.

Date	Status	Part	Serial	Model	Description
2013/12/20	OK	Steel Case	88888	578	UNIFORM AND EVEN SPINDLES
2013/12/19	OK	Change Bar Screen	88888	578	CHANGE BAR SCREEN
2013/12/18	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/17	OK	Tail	88888	578	Tail
2013/12/16	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/15	OK	Change Bar Screen	88888	578	CHANGE BAR SCREEN
2013/12/14	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/13	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/12	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/11	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/10	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/09	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/08	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/07	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/06	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/05	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/04	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/03	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/02	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B
2013/12/01	OK	778 Broken Bearing	88888	578	REPAIR/REPLACE 778 BROKEN BEARING B

Maintenance logs to automatically document machine service.

New **Gribetz Preventative Maintenance** software can help you keep your machine properly maintained for optimized productivity and extend the life of your machine.



No tools necessary for these Quick-set Paddle Brakes. Easy hand adjustments keep your production moving.



Sturdy new bag closer rail system. Splice materials quickly and efficiently.



Wireless, remote material run-out sensors. No cords, no tangles, no problem!


**WildStitch Technology Package**

*New Gribetz quilting technology can increase your daily production by up to 25%!*



Revolutionary new software dynamically sews patterns quicker and more accurately than ever before.

Produce intricate Tack & Jump® or Continuous patterns and still keep up with your production schedules.



Global Systems Group® (GSG) is a collection of the world's leading mattress machinery companies. These GSG machinery companies represent leading edge technology in computerized quilting machines and panel cutters; automated and conventional sewing machines; and mattress packaging equipment.



**GLOBAL SYSTEMS GROUP®**

A DIVISION OF *Leggett & Platt*  
INCORPORATED

131 Zapletal Way  
Carthage, MO 64836 USA

800-343-8138 417-237-6254 [www.GSGcompanies.com](http://www.GSGcompanies.com)



\*\* Productivity claims are based on typical industry standards. Actual results will vary depending on a variety of manufacturing conditions.